



Product Change Notification

107337 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107337 - 00
Change Title: Intel(R) Blade Server Ethernet Switch Modules SBCEGBESW1 and SBCEGBESW10, PCN 107337-00, Product Design, Update Firmware to Version 1.43
Date of Publication: March 06, 2007

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Mar 16, 2007
---	--------------

Description of Change to the Customer:

Update the firmware of Intel(R) Blade Server Ethernet Switch Modules SBCEGBESW1 and SBCEGBESW10 to version 1.43, to include enhancements to address known errata. Please view firmware release notes and product Specification Update for detail.

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers, see PCN detail for further information.

Products Affected / Intel Ordering Codes:

Intel(R) Blade Server Ethernet Switch Modules SBCEGBESW1 and SBCEGBESW10									
Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change AA	Pre Change PBA	Post Change Product Code	Post Change MM#	Post Change TA	Post Change AA	Post Change PBA
SBCEGBESW1 880176	880176	D47483- 001	D47486- 002	D47488- 101	SBCEGBESW1	880176	D47483- 002	D47486- 003	D47488- 102
SBCEGBESW10 880175	880175	D47485- 001	D54540- 002	D54542- 101	SBCEGBESW10	880175	D47485- 002	D54540- 003	D54542- 102

Reference Documents / Attachments:

Document: _____ **Location #:** _____

PCN Revision History:

Date of Revision: _____ **Revision Number:** _____ **Reason:** _____

March 6, 2007

00

Originally Published PCN