



Product Change Notification

104913 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 104913 - 00
Change Title: D865GLC, PCN 104913-00, FYI, Add P24 Bios and new Clock Generator
Date of Publication: March 10, 2005

Type of Change Notification:
FYI - (For Your Information)

Key Characteristics of the Change:
Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Apr 07, 2005
---	--------------

Description of Change to the Customer:

1. Upgrading the BIOS to revision P24. The latest BIOS, and release notes are available at: http://developer.intel.com/design/motherbd/lc/lc_bios.htm. Please refer to the release notes that accompany the BIOS for information on issues fixed and feature enhancements.
2. Add new primary components to the bill of materials for clock generator. These primary component additions are needed to ensure continued component supply availability for manufacturing.

Customer Impact of Change and Recommended Action:

This board change is not expected to cause a change to the Microsoft* Windows* operating system's software driver stack.

These hardware changes are being thoroughly evaluated to ensure that there is no quality, reliability or functional implications to our customers. DPSD is not recommending additional qualification of these changes on platforms received from Intel.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Pre-Change TA or AA	Post-Change TA or AA
BLKD865GLC	852439	C28903-410	C28903-411
BLKD865GLCL	852441	C28906-410	C28906-411
BLKD865GLCLK	852443	C28909-413	C28909-414

Affected Product Code	Pre-Change MM#	Pre-Change TA or AA	Post-Change TA or AA
BOXD865GLC	852438	C28903-410	C28903-411
BOXD865GLCL	852440	C28906-410	C28906-411
BOXD865GLCLK	852442	C28909-413	C28909-414
LAD865GLC	852406	C27498-410	C27498-411
LAD865GLCL	852407	C27499-410	C27499-411
LAD865GLCLK	852408	C27500-411	C27500-412

PCN Revision History:

Date of Revision:
March 10, 2005

Revision Number:
00

Reason:
Originally Published PCN