



Product Change Notification

108145 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108145 - 01
Change Title: SHW4URM23,SHW6URM23 and SHW4URM2SA23, PCN 108145-01, Product Design, Class 2:Accessories, AHWIMMPRO2 Changing, Reason for Revision: TA information update, Roadmap update
Date of Publication: January 09, 2008

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jan 18, 2008
---	--------------

Description of Change to the Customer:

Reason for Revision: TA information update, Roadmap update

Intel® Server Management Module Professional Edition (AHWIMMPRO2) is changing to resolve an erratum where incorrect power supply presence entries are occasionally recorded in the System Event Log (SEL).

Customer Impact of Change and Recommended Action:

Customer may want to perform re-qualification, re-test and may require updates to customer documentation.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change MM#	Post Change TA	Post Change PBA
SHW4URM2SA23	885102	D61136-005	N/A	N/A	D61136-006	N/A
SHW4URM23	886993	D35288-012	N/A	N/A	D35288-013	N/A
SHW6URM23	886994	D35290-011	N/A	N/A	D35290-012	N/A
AHWIMMPRO2	885896	D42646-004	D23013-701	896590	D42646-005	D23013-801

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

December 18, 2007

January 9, 2008

Revision Number:

00

01

Reason:

Originally Published PCN

TA information update, Roadmap
update