



Product Change Notification

107986 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107986 - 01
Change Title: S5000PSL and S5000XSL, PCN 107986-01,
Product Design, Software stack update,
Reason for Revision: Updating the BIOS
version to 85
Date of Publication: January 02, 2008

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jan 18, 2008
---	--------------

Description of Change to the Customer:

Reason for Revision: Updating the BIOS version to 85

The software stack to support newest generation of processors and CLTT will be updated as follows:

- BIOS update to revision R0085
- BMC Update to version 62
- FRUSDR update to version 46

Customer Impact of Change and Recommended Action:

Minimal customer validation is required.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change MM#	Post Change TA	Post Change PBA
S5000PSLROMBR 891983	891983	E12273-001	E11027-101	891983	E12273-002	E11027-102
BB5000PSLSASR 892012	892012	E12378-101	E11025-101	895426	E12378-102	E11025-102
BB5000XSLSATAR 892015	892015	E12387-101	E11032-101	895429	E12387-102	E11032-102
S5000PSLSASR 892051	892051	E12267-001	E11025-101	892051	E12267-002	E11025-102
S5000PSLSATAR 891984	891984	E12274-001	E11027-101	891984	E12274-002	E11027-102

BB5000PSLROMBR 892008	892008	E12374-001	E11027-101	895428	E12374-002	E11027-102
BB5000PSLSATAR 892013	892013	E12382-101	E11027-101	895424	E12382-102	E11027-102
SE11025 893694	893694	E20906-101	E11025-101	893694	E20906-102	E11025-102

Reference Documents / Attachments:

Document: _____ **Location #:** _____

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
October 19, 2007	00	Originally Published PCN
January 2, 2008	01	Updating the BIOS version to 85