



# Product Change Notification

## 105179 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 105179 - 00  
**Change Title:** SE7250BD2, PCN 105179-00, FFF, Class 1:  
Fab revision 401  
**Date of Publication:** June 30, 2005

**Type of Change Notification:**  
FFF - (Form-Fit-Function)

**Key Characteristics of the Change:**  
Product Design

## Forecasted Key Milestones:

<b>Date of First Availability of Post-Conversion Material:</b>	Sep 02, 2005
--	--------------

*The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.*

## Description of Change to the Customer:

- 1 - Board Fabrication upgrade to revision -401
- 2 - Upgrade BIOS Revision to P08
- 3 - System Resource CD change to revision -401  
- FRU/SDR revision 6.6.6
- 4 - Updated Configuration labels for value and SCSI SKU's
- 5 - Updated Quick Start Guide for Boxed products
- 6 - Replace current 12V Aux Power Connector with a keyed Power Connector
- 7 - Pull up resistor value change from 50 ohm to 100 ohm to improve video over the Intel Management Module (Advanced) at the following locations: R2B8, R2B9, R2B10, R2B11, R2B12, R2B13, R2B14, R2B15. Refer to TA-0768-2
- 8 - Sys Fan 5 and Sys Fan 6 Headers rotated 90 degrees to improve fan wire placement
- 9 - Minor silkscreen changes to improve readability

## Customer Impact of Change and Recommended Action:

Intel recommends qualification of new Board, BIOS and Firmware to ensure seamless manufacturing integration.

## Products Affected / Intel Ordering Codes:

### Board Products Table

<b>Affected Product Code</b>	<b>Pre-Change MM#</b>	<b>Post-Change MM#</b>	<b>Pre-Change TA or AA</b>	<b>Post-Change TA or AA</b>	<b>Pre-Change PBA</b>	<b>Post-Change PBA</b>
BBDBBSATAD2	870785	874951	D15649-303	D15649-401	D10351-303	D10351-401
BBDBBSCSID2	870784	874953	D15648-303	D15648-401	D10350-303	D10350-401
BBDVBBD2	870762	874952	D15647-303	D15647-401	D10352-303	D10352-401
SE7520BD2SATAD2	870759	870759	D14266-001	D14266-002	D10351-303	D10351-401
SE7520BD2SCSID2	870783	870783	D14264-001	D14264-002	D10350-303	D10350-401
SE7520BD2VD2	870760	870760	D14265-001	D14265-002	D10352-303	D10352-401

### **Reference Documents / Attachments:**

**Document:**

**Location #:**

### **PCN Revision History:**

**Date of Revision:**

June 30, 2005

**Revision Number:**

00

**Reason:**

Originally Published PCN