



Product Change Notification

107205 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107205 - 00
Change Title: Intel Netstructure® DSI162HMP and DSI162LGNHMP, PCN 107205-00, Product Discontinuance, Product Discontinuance of products due to low sales volume
Date of Publication: January 25, 2007

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

Orders are Non-Cancelable and Non-Returnable After:	Jun 30, 2007
Last Product Discontinuance Order Date:	Jun 30, 2007
Last Product Discontinuance Shipment Date:	Sep 30, 2007
Last Product Return Date:	Mar 30, 2007
Technical Support Service Ends:	Dec 31, 2007

Description of Change to the Customer:

Discontinuance of DSI162HMP and DSI162LGNHMP boards. Products are being discontinued due to low sales volume. Specific Product Codes being retired are listed below.

Customer Impact of Change and Recommended Action:

Please determine your remaining demand for the affected products and place orders in accordance with the key milestones listed.

These products will no longer be supported after December 31, 2007. End of Support is defined as the date after which the following support services are no longer available:

- Software availability - download and ordering
- Telephone, email and web support for affected product(s)
 - Customers will be directed to migration product
- Active reproduction of customer-reported issues
- Installation and configuration support
- Technote and application note creation and maintenance
- Issue entry and tracking via issue management tool
- Defect entry. Fixes for unresolved defects will not be pursued nor released in Point or Service Packages, or in a product revision.
- No new Feature Requests will be accepted.

The End of Support date does not impact the terms of any stated hardware product warranty that governs product repair service.

Migration Plan

No migration products are available.

Contact your sales representative for migration information and/or any issues you may have with this Product Discontinuance Plan.

Products Affected / Intel Ordering Codes:

Affected Product Code	Affected MM#
DSI162HMP	870415
DSI162LGNHMP	870437

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

January 25, 2007

00

Originally Published PCN