



Product Change Notification

106795 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106795 - 00
Change Title: D945GNT, PCN 106795-00, Product Material, Improve VReg circuit, update bios version, and update TPM support
Date of Publication: September 26, 2006

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Oct 02, 2006
---	--------------

Description of Change to the Customer:

Update the board bios to version 3996 and improve robustness of the VReg components.

For D945GNTLKR ONLY: update TPM component to include Vista* support.

Customer Impact of Change and Recommended Action:

These changes have been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. UPSD is not recommending additional qualification of these changes on platforms received from Intel. These board changes are expected not to cause a change to the Microsoft* Windows* operating system's software driver stack.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change AA	Pre Change PBA	Post Change AA	Post Change PBA
LAD945GNTL 868958	868958	C96315-405	C96317-405	C96315-406	C96317-406
BLKD945GNTL 869551	869551	C96315-405	C96317-405	C96315-406	C96317-406
BOXD945GNTL 869552	869552	C96315-405	C96317-405	C96315-406	C96317-406
BLKD945GNTLKR 869553	869553	96320-402	C96322-402	C96320-403	C96322-403
BOXD945GNTLKR 869558	869558	96320-402	C96322-402	C96320-403	C96322-403
BOXD945GNTLR	869796	C96324-	C96326-	C96324-	C96326-

869796		402	402	403	403
BLKD945GNTLR 869797	869797	C96324- 402	C96326- 402	C96324- 403	C96326- 403

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

September 26, 2006

00

Originally Published PCN