



# Product Change Notification

## 109218 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apagccb@intel.com](mailto:apagccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 109218 - 00  
**Change Title:** Intel® Storage System SSR212MC2, PCN 109218-00, Product Material, Factory Change and Firmware Updates  
**Date of Publication:** March 04, 2009

## Key Characteristics of the Change:

Product Material

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Mar 30, 2009
---	--------------

## Description of Change to the Customer:

SSR212MC2RBR and SSR212MC2BR:

The Intel® RAID Controller SRCAS144E firmware is being updated to v1.12.200-0527, see the firmware release notes for details of the changes;

The boot drive PBA power connector is being changed to a through-hole mount to improve connector durability;

The top cover lock is being changed to improve durability;

The system fans are being change to aluminum to improve hard disk drive rotational vibration performance;

The power supply unit module firmware is being updated to improve acoustics.

FMCBOOTENCL:

The boot drive PBA power connector is being changed to a through-hole mount to improve connector durability.

FMCFANSHS:

The system fans are being change to aluminum to improve hard disk drive rotational vibration performance;

AMC850WPS:

The power supply unit module firmware is being updated to improve acoustics.

## Customer Impact of Change and Recommended Action:

Customers should review the Intel® RAID Controller SRCAS144E firmware release notes and evaluate the firmware, if needed. Customers may also want to evaluate the power connector, top cover lock, and power supply firmware changes when available.

## Products Affected / Intel Ordering Codes:

Pre Change	Pre Change	Pre Change	Post Change	Post Change	Post Change
------------	------------	------------	-------------	-------------	-------------

<b>Product Code</b>	<b>MM#</b>	<b>TA</b>	<b>Product Code</b>	<b>MM#</b>	<b>TA</b>
SSR212MC2BR	893628	D88964-009	SSR212MC2BR	893628	D88964-010
SSR212MC2RBR	893519	D88965-009	SSR212MC2RBR	893519	D88965-010
FMCFANSHS	891941	E12588-002	FMCFANSHS	891941	E12588-003
FMCBOOTENCL	896756	D89366-002	FMCBOOTENCL	896756	D89366-002
AMC850WPS	890400	D89372-002	AMC850WPS	890400	D89372-003

**Reference Documents / Attachments:**

**Document:**

**Location #:**

**PCN Revision History:**

**Date of Revision:**

**Revision Number:**

**Reason:**

March 4, 2009

00

Originally Published PCN