



Product Change Notification

103793 - 04

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2004. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash, Trillium is a trademark or registered trademarks of Intel corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 103793 - 04
Change Title: SR2300, PCN 103793-04, FYI, Class 2;
Updated SCSI Backplane hot swap controller
code (HSC)
Date of Publication: March 22, 2004

Type of Change Notification:
FYI - (For Your Information)

Key Characteristics of the Change:
Software

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Mar 26, 2004
---	--------------

Description of Change to the Customer:

Updated SCSI Backplane hot swap controller code (HSC) from version .0005 to version .0006. This change is to add support for larger sized hard drives.

Customer Impact of Change and Recommended Action:

Updated SCSI Backplane hot swap controller code (HSC) from version .0005 to version .0006. This change is to add support for larger sized hard drives - Customer needs to be aware of the change; no impact to customer expected.

Products Affected / Intel Ordering Codes:

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
KSW	854056	861031	A81074-019	A81074-020	A79488-303/304	A79488-305
KSW480	854197	854197	A88341-015	A88341-016	A79488-303/304	A79488-305
SE7501WV2SKU02	855630	861032	C22264-016	C22264-017	A79488-303/304	A79488-305
SWV2USKU07	853492	861062	C32002-011	C32002-012	A79488-303/304	A79488-305

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
FSWELECTKT	847309	847309	A90868-005	A90868-006	A79488-303/304	A79488-305

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
December 17, 2003	00	Originally Published PCN
January 22, 2004	01	Implementation date has changed to 3/12/04
January 22, 2004	02	TA# Correction make to SKU SWV2USKU07
February 10, 2004	03	Updating TA numbers
March 22, 2004	04	Update MM#; TA# & available date