



Product Change Notification

103874 - 01

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2004. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash, Trillium is a trademark or registered trademarks of Intel corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 103874 - 01
Change Title: SR2300, PCN 103874-01, FYI, Class 2;
Capacitor Change on the 3.3V Riser Card
Date of Publication: February 10, 2004

Type of Change Notification:
FYI - (For Your Information)

Key Characteristics of the Change:
Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Mar 05, 2004
---	--------------

Description of Change to the Customer:

Changing capacitor value at positions C2, C3, C6 & C8 from 10uf 6.3V to 4.7uf 16.0V on the 3.3V riser card. This change is to increase voltage margin on the capacitor. This change does not change the functionality of this product.

Customer Impact of Change and Recommended Action:

Changing capacitor value at positions C2, C3, C6 & C8 from 10uf 6.3V to 4.7uf 16.0V on the 3.3V riser card. This change is to increase voltage margin on the capacitor. This change does not change the functionality of this product - Customer needs to be aware of the change; no impact to customer expected.

Products Affected / Intel Ordering Codes:

System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
KSW	854056	854056	A88341-018	A88341-019		
KSW480	854197	854197	A88341-014	A88341-015		
SE7501WV2SKU02	855630	855630	C22266-015	C22266-016		
SWV2USKU07	853492	853492	C32002-009	C32002-010		

Component Product Table

Pre-Conversion Product Code	Pre-Conversion Spec/ROM	Pre-Conversion MM#	Post-Conversion Product Code	Post-Conversion Spec/ROM	Post-Conversion MM#
FSW2URISERS	C57737-004	857785	FSW2URISERS	C57737-005	
FSWELECTKT	A90868-004	847309	FSWELECTKT	A90868-005	

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

February 9, 2004

00

Originally Published PCN

February 10, 2004

01

Updating TA numbers