



# Product Change Notification

## 104683 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2004. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 104683 - 02  
**Change Title:** D910GLDW, D915GVWB, PCN 104683-02, FFF, Update BIOS, Remove mic logo, SIO revision.

**Date of Publication:** December 29, 2004

**Type of Change Notification:**  
FFF - (Form-Fit-Function)

**Key Characteristics of the Change:**  
Manufacturing Site

## Forecasted Key Milestones:

<b>Date of Samples Availability:</b>	Jan 08, 2005
--------------------------------------	--------------

## Description of Change to the Customer:

1. Updated BIOS to 0690, please see release notes at: [http://www.intel.com/design/motherbd/wb/wb\\_bios.htm](http://www.intel.com/design/motherbd/wb/wb_bios.htm)
2. Add ICH GPIO pull up resistor R7H9 0 ohm.
3. Remove MIC logo
4. Revise National Semiconductor (r) SIO U1J1 A3 stepping

## Customer Impact of Change and Recommended Action:

These board changes have been thoroughly evaluated to ensure that there is no quality or reliability implications.

These changes ARE expected to affect the Microsoft\* Windows\* operating system's software driver stack, or software image stack due to a subsystem vendor ID change. The changes have been thoroughly evaluated to ensure that there is no quality, reliability or HW functional implications to our customers.

## Products Affected / Intel Ordering Codes:

### Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BLKD910GLDW 865191	865191	865191	C82202-102	C82202-103		
BLKD910GLDWL 865193	865193	865193	C82203-102	C82203-103		
BLKD915GVWB 867075	867075	867075	C82204-102	C82204-103		
BLKD915GVWBL 867068	867068	867068	C82205-102	C82205-103		

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
BOXD910GLDW 865190	865190	865190	C82202-102	C82202-103		
BOXD910GLDWL 865192	865192	865192	C82203-102	C82203-103		
BOXD915GVWB 867070	867070	867070	C82204-102	C82204-103		
BOXD915GVWBL 867071	867071	867071	C82205-102	C82205-103		
LAD910GLDWL 865020	865020	865020	C82194-102	C82194-103		
LAD915GVWBL 865018	865018	865018	C81885-101	C81885-102		

### Reference Documents / Attachments:

Document:

Location #:

### PCN Revision History:

Date of Revision:

Revision Number:

Reason:

December 27, 2004

00

Originally Published PCN

December 28, 2004

01

Changed efectivity date

December 29, 2004

02

For MM865193, the AA should be C82203- instead of C8220, this was added on a later ECO change list