



Product Change Notification

106528 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

America's OEM's Contact:

Lester Dimit

Phone:(503) 712-8272

Email: lester.dimit@intel.com

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106528 - 01

Change Title: Intel® PRO/Wireless 3945ABG Network Connection Gen Skus: WM3945AGM1GEN, M2GEN, RWGEN, JPGEN, KRGEN, BGGEN, BGXGEN, (MM#s 872612, 872659, 874511, 874740, 874738, 874652, 878806), PCN 106528-01, Label, OUI Replenishment, Reason for Revision: Factory request to dash the TA# for better change management

Date of Publication: July 14, 2006

Key Characteristics of the Change:

Label

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Aug 04, 2006
Date of First Availability of Post-Conversion Material:	Aug 04, 2006

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

Intel has depleted the available 3945ABG MAC addresses in the current OUI block more quickly than original forecast. Allocation of MAC addresses in OUI 00-13-02 will be exhausted by the end of WW31 (8/4/06). The change is required to continue to provide 3945ABG supply to Intel's customers.

Description of change:

First 6 characters will change:

Pre-Conversion: 00-13-02

Post-Conversion: 00-18-DE

Customer Impact of Change and Recommended Action:

Customer will receive the Intel PRO/Wireless 3945ABG Network Connection with the new MAC addresses with a change in the first 6 characters and a new dash of the TA# on the label.

New OUI (Organization Unique Identifier) block for all 3945 skus

<u>Current OUI</u>	<u>New OUI</u>
00-13-02	00-18-DE
(OUIP = C97400)	(OUIP = D67847)

Intel will attempt to deplete pre-conversion material before shipping post-conversion material but there is a possibility of Intel shipping mixed inventory. Therefore, customers will need to manage and migrate to the post-conversion material as soon as possible.

For your information only. No change to form fit or function. No change to Intel Ordering codes.

Milestone dates are estimates and subject to change based on business and operational conditions.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
WM3945AGBGGGEN	874652	874652	D26430-007	D26430-008	D26890-004	D26890-004
WM3945AGBGXGEN	878806	878806	D42007-002	D42007-003	D26890-004	D26890-004
WM3945AGJPGEN	874740	874740	D26428-010	D26428-011	D26890-004	D26890-004
WM3945AGKRGGEN	874738	874738	D26429-008	D26429-009	D26890-004	D26890-004
WM3945AGM1GEN	872612	872612	D26965-007	D26965-008	D26890-004	D26890-004
WM3945AGM2GEN	872659	872659	D26839-007	D26839-008	D26890-004	D26890-004
WM3945AGRWGEN	874511	874511	D26427-008	D26427-009	D26890-004	D26890-004

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

July 12, 2006

00

Originally Published PCN

July 14, 2006

01

Factory request to dash the TA# for better change management