



Product Change Notification

112508 - 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2013. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #:	112508 - 00
Change Title:	Intel® 10 Gigabit AF DA Dual Port Server Adapter (Long Cove) SKU E10G42AFDA MM#897657 Retail Intel® 10 Gigabit CX4 Dual Port Server Adapter (Cedar Cove) SKU EXPX9502CX4 MM#895897 Retail PCN 112508-00 Product Discontinuance End of Life
Date of Publication:	August 30, 2013

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

	ALL PRODUCTS
Product Discontinuance Program Support Begins:	Sep 01, 2013
Last Product Discontinuance Order Date:	Mar 01, 2014
Last Product Discontinuance Shipment Date:	Sep 01, 2014
	For MM#895897 Only
Last Product Return Date: (Only for SKU: EXPX9502CX4 MM#895897)	Sep 01, 2014
Technical Support Service Ends: (Only for SKU: EXPX9502CX4 MM#895897)	Sep 01, 2015

Description of Change to the Customer:

Intel is announcing the discontinuance of the Intel® 10 Gigabit AF DA Dual Port Server Adapter and Intel® 10 Gigabit CX4 Dual Port Server Adapter as of 9/01/2013. The last day for orders will be 3/01/2014. Delivery of all orders must be taken no later than 9/01/2014. See table below for replacement SKU options.

Customer Impact of Change and Recommended Action:

Please contact your local Intel Field Sales representative if you have any further questions about this End of Life notice.

Note on Discontinued Product Returns:

Approval from Intel, documented by an RMA# reference, must be obtained prior to the return of any product. No credit will be given for products returned by a distributor without prior authorization from Intel and unauthorized returns will be returned to the distributor, freight collect. Intel reserves the right to refuse credit if upon receipt of product it establishes that the terms of return, as defined in this policy, have not been met by distributor or if the product returned does not match the product described on the authorized RMA. Credit for returned products will be calculated based on the cost specified in the current Distributor Cost List in effect on the day that the return is authorized by Intel. Products included in the Discontinued Product Return Notification, as described in Product Discontinuance policy #188000, are not eligible for return under any other Intel® RMA program. No returns of any kind will be accepted for shrink-wrap software products if the shrink-wrap is broken. As indicated below, certain types of RMA product must be returned in the original unopened, undamaged, and unadjusted packaging. Where this requirement is not met, Intel reserves the right to return the product to distributor, freight collect, or to charge distributor a 20% administration fee when calculating credit for return. It is the responsibility of the distributor to ensure that RMA product is adequately protected to reasonably ensure that damage in-transit to Intel does not occur.

Products Affected / Intel Ordering Codes:

Product Name	Product Code	MM#	Recommended Replacement Product Code	Recommended Replacement MM#	Recommended Replacement SKU Comments
Intel® 10 Gigabit AF DA Dual Port Server (Long Cove) Retail	E10G42AFDA	897657	E10G42BTDA	900139	
Intel® 10 Gigabit CX4 Dual Port Server Adapter (Cedar Cove) Retail	EXPX9502CX4	895897	E10G42BTDA	900139	The suggested replacement SKU is not a direct CX4 replacement. Customers will need to qualify to ensure it works in their application/system.

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
August 30, 2013	00	Originally Published PCN