



# Product Change Notification

## 105732 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

**Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.**

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 105732 - 02  
**Change Title:** Intel Entry Server SR1475, SR1475NA, SR1475NH1 and SR1475NH1NA, PCN 105732-02, Product Material, Class 2, System fan is changing from a three wire to a four wire fan, Reason for Revision: The change will be implemented at a later date  
**Date of Publication:** March 20, 2006

## Key Characteristics of the Change:

Product Material

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	May 05, 2006
<b>Date of First Availability of Post-Conversion Material:</b>	May 05, 2006

*The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.*

## Description of Change to the Customer:

**Reason for Revision:** The change will be implemented at a later date

The System Fan is being changed from a three wire to a four wire fan. The change will allow the system fan to operate at speeds other than full speed and will improve acoustic levels of the system. This fan cools the PCI Slot and the first hard drive bay.

## Customer Impact of Change and Recommended Action:

Evaluate when received. Fan management changes are not required by the customer.

## Products Affected / Intel Ordering Codes:

### System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
SR1475	873809		D23429-004	TBD		

<b>Affected Product Code</b>	<b>Pre-Change MM#</b>	<b>Post-Change MM#</b>	<b>Pre-Change TA</b>	<b>Post-Change TA</b>	<b>Pre-Change Subassembly</b>	<b>Post-Change Subassembly</b>
SR1475NA	874472		D23429-004	TBD		
SR1475NH1	873808		D23430-004	TBD		
SR1475NH1NA	874473		D23430-004	TBD		

### **Reference Documents / Attachments:**

**Document:**

**Location #:**

### **PCN Revision History:**

**Date of Revision:**

**Revision Number:**

**Reason:**

December 13, 2005

00

Originally Published PCN

December 15, 2005

01

Product TA Numbers were incorrectly published

March 20, 2006

02

The change will be implemented at a later date