



# Product Change Notification

## 103575 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2003. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash, Trillium is a trademark or registered trademarks of Intel corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 103575 - 00  
**Change Title:** SE7501WV2, PCN 103575-00, FYI, Class 2;  
Resource CD Update and Server  
Management CD Update  
**Date of Publication:** September 02, 2003

**Type of Change Notification:**  
FYI - (For Your Information)

**Key Characteristics of the Change:**  
Software

## Forecasted Key Milestones:

<b>Date of First Availability of Post-Conversion Material:</b>	Aug 15, 2003
----------------------------------------------------------------	--------------

*The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.*

## Description of Change to the Customer:

Resource CD Update - Part number change from C12502-002 to C12502-004:  
Changes to include updated drivers.  
Server Management CD Update - Part number change from A96171-002  
version 5.5 to A96171-005 version 5.5.3; see CD release notes for  
details.

## Customer Impact of Change and Recommended Action:

Resource CD Update - Part number change from C12502-002 to C12502-004:  
Changes to include updated drivers - Customer needs to be aware of the  
change; no impact to customer expected.  
Server Management CD Update - Part number change from A96171-002  
version 5.5 to A96171-005 version 5.5.3; see CD release notes for  
details - Customer needs to be aware of the change; no impact to  
customer expected.

## Products Affected / Intel Ordering Codes:

### System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
SE7501WV2SKU02	855630	855630	C22264-009	C22264-010	C12502-002	C12502-002

### Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
SE7501WV2ATA	851374	851374	C12309-002	C12309-003	A99388-109	A99388-110
SE7501WV2SCSI	851370	851370	C12308-002	C12308-003	A99386-109	A99386-110

### Reference Documents / Attachments:

Document:

Location #:

### PCN Revision History:

Date of Revision:

Revision Number:

Reason:

September 2, 2003

00

Originally Published PCN