



# Product Change Notification

## 107229 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #: 107229 - 01**

**Change Title: D946GZTS, PCN 107229-01,  
Product Marking, Add RoHS label  
for PRC and EI-CD refresh for  
Windows Vista, Reason for  
Revision: error in product name in  
description to the customer**

**Date of Publication: February 11, 2007**

## Key Characteristics of the Change:

Product Marking

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Mar 08, 2007
---	--------------

## Description of Change to the Customer:

**Reason for Revision: error in product name in description to the customer**

Add the RoHS markings to the D946GZTS Intel Desktop Board as a requirement for the People's Republic of China for retail products manufactured on or after 1 March 2007. The markings will appear as a label on the component side of the printed circuit board and on the motherboard packaging as well.

An updated Express Installer CD for Microsoft Windows Vista will be included as well.

## Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. CDPG is not recommending additional qualification of these changes on platforms received from Intel. These board changes are not expected to cause a change to the Microsoft\* Windows\* operating system's software driver stack. No expected OS image change.

## Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change AA	Pre Change PBA	Post Change TA	Post Change AA	Post Change PBA
-------------------------	----------------	---------------	---------------	----------------	----------------	----------------	-----------------

BOXD946GZTSSL 882971	882971	D59259- 100	D43871- 402	D43872- 402	D59259- 101	D43871- 403	D43872- 403
BLKD946GZTSSL 882975	882975	D59262- 100	D43871- 402	D43872- 402	D59262- 101	D43871- 403	D43872- 403

### Reference Documents / Attachments:

**Document:**

**Location #:**

### PCN Revision History:

**Date of Revision:**

**Revision Number:**

**Reason:**

February 11, 2007

00

Originally Published PCN

February 11, 2007

01

error in product name in  
description to the customer