



# Product Change Notification

## 106796 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: <mailto:asmo.pcn@intel.com>

Asia Pacific Contact: <mailto:apacgccb@intel.com>

Europe Email: <mailto:eccb@intel.com>

Japan Email: <mailto:jccb.ijkk@intel.com>

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 106796 - 01  
**Change Title:** DQ965CO, PCN 106796-01, Product Design, Update BIOS, component change, add alt DIMM connector, Reason for Revision: Revise post change MM#  
**Date of Publication:** October 09, 2006

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Sep 28, 2006
---	--------------

## Description of Change to the Customer:

### Reason for Revision: Revise post change MM#

Updated BIOS to improve iAMT functionality. Updated capacitors to improve voltage regulator circuitry. Added alternate DIMM connector to improve manufacturability.

## Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. These board changes are not expected to cause a change to the Microsoft\* Windows\* operating system's software driver stack. No expected OS image change.

## Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change AA	Pre Change PBA	Post Change MM#	Post Change AA	Post Change PBA
LADQ965COKR 878122	878122	D34641-502	D34642-502	878122	D34641-503	D34642-503
BLKDQ965COEKR 878943	878943	D37070-502	D37071-502	878943	D37070-503	D37071-503
BOXDQ965COEKR 878945	878945	D37070-502	D37071-502	878945	D37070-503	D37071-503

## Reference Documents / Attachments:

**Document:**

**Location #:**

## **PCN Revision History:**

<b>Date of Revision:</b>	<b>Revision Number:</b>	<b>Reason:</b>
September 21, 2006	00	Originally Published PCN
October 9, 2006	01	Revise post change MM#