



Product Change Notification

104223 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geography location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2004. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 104223 - 00
Change Title: BCPT1X32R2PCI, BCP30X32R2EUPCI,
PCN 104223-00, PD, Product Discontinuance
due to End of Life of Constituent Board
Components and Availability of Improved
Products
Date of Publication: July 15, 2004

Type of Change Notification:
PD - (Product Discontinuance)

Key Characteristics of the Change:
Product Discontinuance

Forecasted Key Milestones:

Product Discontinuance Program Support Begins:	Jul 15, 2004
Last Product Discontinuance Order Date:	Jan 01, 2005
Last Product Discontinuance Shipment Date:	Apr 02, 2005

Description of Change to the Customer:

Due to End of Life of constituent board components and availability of improved products two BCP products are being discontinued. Specific Product Codes being retired are listed below.

Customer Impact of Change and Recommended Action:

Please determine your remaining demand for the affected product and place orders in accordance with the key milestones listed.
Last Product Return Date is October 2, 2004. Orders are non-cancelable and non-returnable after October 2, 2004.

Contact your sales representative for additional migration information and/or any issues you may have with this Product Discontinuance Plan.

Migration Plan

The following BCP products are recommended as migration products.

<u>Product Names</u>	<u>MM</u>	<u>Migration Product</u>	<u>MM</u>
BCPT1X32R2PCI	852844	BCPT1X32R3PCI	861963
BCPT1X32R2PCI	854670	BCPT1X32R3PCI	861963
BCPT1X32R2PCI	855080	BCPT1X32R3PCI	861963
BCP30X32R2EUPCI	852846	BCP30X32R3EUPCI	862051
BCP30X32R2EUPCI	854671	BCP30X32R3EUPCI	862051
BCP30X32R2EUPCI	855081	BCP30X32R3EUPCI	862051

Products Affected / Intel Ordering Codes:

System Products Table

Affected Product Code	Affected MM#
BCPT1X32R2PCI	852844
BCPT1X32R2PCI	854670
BCPT1X32R2PCI	855080*
BCP30X32R2EUPCI	852846
BCP30X32R2EUPCI	854671
BCP30X32R2EUPCI	855081*

Active Products are denoted by *

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

July 15, 2004

00

Originally Published PCN