



Product Change Notification

111486 - 03

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2013. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 111486 - 03
Change Title: Intel® Server System R1208GZ4GC, R1304GZ4GC, R2208GZ4GC and R2308GZ4GC
PCN 111486-03, Product Design, System Top Cover Updated and Changing BBU Bracket Length
Reason for Revision: Remove Product Code R2308GZ4GC MM#917004 from ASMO LSIC SKU Table; Add additional change for R1304GZ4GC
Date of Publication: November 12, 2013

Key Characteristics of the Change:
Product Design

Forecasted Key Milestones:

	ASMO LSIC SKU	EMEA LSIC SKU
Date Customer Must be Ready to Receive Post-Conversion Material *:	July 24, 2012	July 24, 2012

* Intel appreciates the customer's desire to receive the latest revision of products. However, Intel manages inventory on a first in first out (FIFO) basis at the MM# level. Subsequently, customer requests for a specific revision of material (below the MM#) will not be supported by Intel.

Description of Change to the Customer:

Reason for Revision: Remove Product Code R2308GZ4GC MM#917004 from ASMO LSIC SKU Table; Add additional change for R1304GZ4GC

Intel has implemented the following changes at factory:

For Intel® Server System R1208GZ4GC:

1. Updated the top cover to improve fit tolerances.
2. Updated the Quick User's Installation Guide from G31060-003 to G31060-004 with new installation instructions for installing top cover screws.
3. Changed the BBU bracket length to accommodate all system chassis.

For Intel® Server System R2208GZ4GC and Intel® Server System R2308GZ4GC:

1. Updated the top cover to improve fit tolerances.
2. Updated the Quick User's Installation Guide from G31061-003 to G31061-004 with new installation instructions for installing top cover screws.

For Intel® Server System R1304GZ4GC:

1. Updated the top cover to improve fit tolerances.
2. Updated the Quick User's Installation Guide from G31060-003 to G31060-004 with new installation instructions for installing top cover screws.
3. Changed the BBU bracket length to accommodate all system chassis.
4. [Change eUSB SSD Stand-off with a strengthened version that holds part more securely.](#)

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers, no action is recommended or required.

Products Affected / Intel Ordering Codes:

ASMO LSIC SKU			
Product Code	MM#	Pre Change TA	Post Change TA
R1304GZ4GC	916994	G50534-001	G50534-002
R1208GZ4GC	916995	G52084-001	G52084-002
R2208GZ4GC	917001	G52127-001	G52127-002

EMEA LSIC SKU			
Product Code	MM#	Pre Change TA	Post Change TA
R1304GZ4GC	916994	G50533-001	G50533-002
R1208GZ4GC	916995	G52083-001	G52083-002
R2208GZ4GC	917001	G52125-001	G52125-002
R2308GZ4GC	917004	G52105-001	G52105-002

Product Affected / Intel Order Code(s) removed from PCN:

ASMO LSIC SKU		
Product Code	MM#	TA #
R2308GZ4GC	917004	G52106-001

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
May 14, 2012	00	Originally Published PCN
July 23, 2012	01	Core SKUs removed. See PCN111618-00 for Core Sku Change.
March 12, 2013	02	Correcting TA#s incorrectly associated with MM#s and Removed PBA#s
November 12, 2013	03	Remove Product Code R2308GZ4GC MM#917004 from ASMO LSIC SKU Table; Add additional change for R1304GZ4GC