



Product Change Notification

103293 - 01

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel® products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel® products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geography location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: Your local account representative

Asia Pacific Contact: Your local account representative

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com

Copyright © Intel Corporation 2003. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANdesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash, Trillium is a trademark or registered trademarks of Intel corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 103293 - 01
Change Title: D865PERL, PCN 103293-01, FYI, BIOS update, add alternate SIO part
Date of Publication: May 07, 2003

Type of Change Notification:
FYI - (For Your Information)

Key Characteristics of the Change:
Product Design

Forecasted Key Milestones:

Date of First Availability of Post-Conversion Material:	May 19, 2003
--	--------------

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

1. Replace A78930-001 with C18424-002 as the alternate SIO part. This change in the alternate SIO part is needed to ensure component availability for manufacturing.
2. Add BIOS P06. This BIOS and release notes will be available at <http://developer.intel.com/design/motherbd/> and listed under the D865PERL.

Customer Impact of Change and Recommended Action:

These board changes are not expected to cause a change to the Microsoft* Windows* operating system's software driver stack.

The changes have been thoroughly evaluated to ensure that there is no quality, reliability or functional implication to our customers. DPSD is not recommending additional qualification of these changes on platforms received from Intel.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA
BLKD865PERL	852515	852515	C27648-206	C27648-207
BLKD865PERLK	852519	852519	C26719-207	C26719-208
BLKD865PERLL	852517	852517	C27646-206	C27646-207
BOXD865PERL	852514	852514	C27648-206	C27648-207
BOXD865PERLK	852518	852518	C26719-207	C26719-208
BOXD865PERLL	852516	852516	C27646-206	C27646-207
LAD865PERLL	852488	852488	C27650-206	C27650-207

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

April 25, 2003

00

Originally Published PCN

May 7, 2003

01

Update the BIOS revision to be included in this product change.