



Product Change Notification

105819 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 105819 - 02
Change Title: SR4850HW4 and SR6850HW4 Servers and FHWSATAIDE Spare, PCN 105819-02, Product Material, CLASS 2: Change the ISM and Resource CDs; change SHW6UR rack handles and RoHS SATA board, Reason for Revision: Add FHWSATAIDE to PCN. Add RoHS statement. Change PB-Free
Date of Publication: February 22, 2006

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Feb 17, 2006
---	--------------

Description of Change to the Customer:

Reason for Revision: Add FHWSATAIDE to PCN. Add RoHS statement. Change PB-Free to RoHS.

SR4850HW4 (SHW4UR):
874581

- Change the top assembly part number from C92307-007 to C92307-008
- Change the accessory option from C68643-003 to C68643-004
- Change the resource CD from C91330-005 to C91330-006
- Change the ISM CD from C63395-006 to C63395-007
- ISM CD version: 8.40
- Change the SATA board part number from C71688-001 to C71688-002
- Restriction of Hazardous Substances (RoHS) compliant

SHW6850HW4 (SHW6UR):
874583

- Change the top assembly part number from C92308-007 to C92308-008
- Change the accessory option from D10872-002 to D10872-003
- Change the resource CD from C91330-005 to C91330-006
- Change the ISM CD from C63395-006 to C63395-007
- ISM CD version: 8.40
- Change the SATA board part number from C71688-001 to C71688-002
- Restriction of Hazardous Substances (RoHS) compliant
- Change rack handle part number from C70638-002, to C70638-003
- Added slit in handle

FHWSATAIDE :
870273

Change the top assembly part number from D10881-001 to D10881-002
Change the SATA board part number from C71688-001 to C71688-002
Restriction of Hazardous Substances (RoHS) compliant

Customer Impact of Change and Recommended Action:

This change does not impact performance, quality, reliability, interchangeability, functionality or customer handling and manufacturability.

Products Affected / Intel Ordering Codes:

System Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
FHWSATAIDE	870273	870273	D10881-001	D10881-002	C71688-001	C71688-002
SHW4UR	874581	874581	C92307-007	C92307-008		
SHW6UR	874583	874583	C92308-007	C92308-008		

Reference Documents / Attachments:

Document: _____ **Location #:** _____

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
January 10, 2006	00	Originally Published PCN
February 13, 2006	01	Change implementation date Add SHW6UR handle change Add PB-free SATA board
February 22, 2006	02	Add FHWSATAIDE to PCN. Add RoHS statement. Change PB-Free to RoHS.