



Product Change Notification

106990 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106990 - 01
Change Title: Intel NetStructure (R) MPCBL0030 Single Board Computer, PCN 106990-01, Product Design, Change of BIOS to 05.P. Change of IPMC FW to 1.7.5., Reason for Revision: Change reference for new features and bug fixes to Software Release Notes
Date of Publication: February 01, 2007

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Apr 30, 2007
---	--------------

Description of Change to the Customer:

Reason for Revision: Change reference for new features and bug fixes to Software Release Notes

1. Firmware (BIOS, IPMC, FPGA) changes as follows:

BIOS from P.03 to P.05

IPMC Firmware from 1.3.1 to 1.7.5

FPGA remains at B.006

Changes to the BIOS and IPMC Firmware releases with full release notes can be found at the following link:

<http://www.intel.com/design/telecom/products/cbp/atca/9635/tools.htm>

Note: The FPGA should be updated to version B.006 and the BIOS updated to at least Version 04.P in conjunction with upgrading to version 1.7.5 of the IPMC FW. This is necessary for proper operation of Fault Resilient Booting (FRB).

Customer Impact of Change and Recommended Action:

This is a change to the BIOS and IPMC FW. Customer may wish to retest and re-certify.

Code is available for download at:

<http://www.intel.com/design/telecom/products/cbp/atca/9635/tools.htm>

Products Affected / Intel Ordering Codes:

Pre Change	Pre Change	Pre Change	Post Change	Post Change
------------	------------	------------	-------------	-------------

Product Code	MM#	TA	MM#	TA
MPCBL0030 874545	874545	D26196-006	874545	D26196-007

Reference Documents / Attachments:

Document: _____ **Location #:** _____

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
January 19, 2007	00	Originally Published PCN
February 1, 2007	01	Change reference for new features and bug fixes to Software Release Notes