



Product Change Notification

107224 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107224 - 01
Change Title: D945GCZ, PCN 107224-01, Product Marking, Add RoHS label for PRC, Reason for Revision: Update ready to receive date
Date of Publication: February 04, 2007

Key Characteristics of the Change:
Product Marking

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Mar 15, 2007
---	--------------

Description of Change to the Customer:

Reason for Revision: Update ready to receive date

Add the RoHS markings to the D945GCZ Intel Desktop Board as a requirement for the People's Republic of China for retail products manufactured on or after 1 March 2007. The markings will appear as a label on the component side of the printed circuit board and on the motherboard packaging as well.

Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. CDPG is not recommending additional qualification of these changes on platforms received from Intel. These board changes are not expected to cause a change to the Microsoft* Windows* operating system's software driver stack. No expected OS image change.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change AA	Pre Change PBA	Post Change AA	Post Change PBA
LAD945GCZLKR 868924	868924	C99567-506	C99568-506	C99567-507	C99568-507
LAD945GCZLK 868926	868926	D10253-503	D10254-503	D10253-504	D10254-504
BOXD945GCZLKR 869569	869569	C99567-506	C99568-506	C99567-507	C99568-507
BLKD945GCZLKR 869570	869570	C99567-506	C99568-506	C99567-507	C99568-507

BOXD945GCZL 869573	869573	C99368-503	C99370-503	C99368-504	C99370-504
BLKD945GCZL 869574	869574	C99368-503	C99370-503	C99368-504	C99370-504
BLKD945GCZLR 869576	869576	D10312-503	D10313-503	D10312-504	D10313-504
BOXD945GCZLR 869579	869579	D10312-503	D10313-503	D10312-504	D10313-504
LAD945GCZCS 869689	869689	D10307-506	D10310-506	D10307-507	D10310-507

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

January 25, 2007

00

Originally Published PCN

February 4, 2007

01

Update ready to receive date