



Product Change Notification

105038 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2005. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 105038 - 00
Change Title: Intel(R) Entry Server Board SE7221BA1-E,
PCN 105038-00, FYI, CLASS 03: UPDATE
REV 1.8 MARVELL LAN EEPROM
DATAFILE
Date of Publication: April 22, 2005

Type of Change Notification:
FYI - (For Your Information)

Key Characteristics of the Change:
Software

Forecasted Key Milestones:

Date of First Availability of Post-Conversion Material:	May 09, 2005
--	--------------

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

The Marvell Yukon 88E8050 Network controller EEPROM datafile will be updated to v1.8 from v1.7 at the factory. This change corrects remote connection failures during Microsoft(R) Windows 2003 WHQL testing. The EEPROM on C83889-301 boards and earlier may be user updated with RAWINT18.EXE utility available on the support web site.

Customer Impact of Change and Recommended Action:

Evaluate when recieved.

Products Affected / Intel Ordering Codes:

Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
SE7221BA1 868624	868624	868624	C83389-301	C83389-302	C83389-301	C83389-302

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

April 22, 2005

Revision Number:

00

Reason:

Originally Published PCN