



Product Change Notification

107385 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107385 - 01
Change Title: Intel(R) IXP12xx Family Network Processors, PCN 107385-01, Product Discontinuance, Reason for Revision: Replace IXP1250 with IXP12xx for Clarification Purposes
Date of Publication: March 22, 2007

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

Product Discontinuance Program Support Begins:	Mar 16, 2007
Last Product Discontinuance Order Date:	Mar 17, 2008
Last Product Discontinuance Shipment Date:	Sep 16, 2008

Description of Change to the Customer:

Reason for Revision: Replace IXP1250 with IXP12xx for Clarification Purposes

Intel is announcing the discontinuance of the IXP12xx listed in the Affected Product table listed below. These products will be unavailable for additional orders after the "Last Product Discontinuance Order Date" (see "Forecasted Key Milestones" above).

Intel is extending the "Last Product Discontinuance Order Date" and "Last Product Discontinuance Shipment Date" for the Pb products listed in the PCN that were also listed in PCN 105988-01 to align with the Forecasted Key Milestones with this PCN - #107385. The synchronization of these dates is being implemented to minimize customer transitions. The affected product list is included in the body of this Product Change Notification.

Customer Impact of Change and Recommended Action:

Customers are requested to determine their remaining demand for the IXP12xx Processor line items affected by this PCN and place their "Last Product Discontinuance Orders" in accordance with the "Forecasted Key Milestones" listed above.

Customers with supply requirements for IXP12xx beyond the horizon of this PCN should consider IXP2300-based designs. However, replacement of the IXP12xx Processor may require varying degrees of engineering design consideration. The IXP2300 Processors are not pin-for-pin replacements for the IXP12xx Processors. Intel recommends customers reference data sheet for IXP2300 and perform necessary validation to determine which replacement part is appropriate.

Products Affected / Intel Ordering Codes:

Product Code	MM#
GCIXP1200GC 839429	839429
GCIXP1200GB 838428	839428
GCIXP1200GA 838427	839427
GCIXP1240AC 837152	837152
GCIXP1240AB 837151	837151
GCIXP1250BC 837414	837414
GCIXP1250BB 837412	837412
GCIXP1250BA 837411	837411
GCIXP1250BAT 837416	837416
QCIXP1200GC 863762	863762
QCIXP1200GB 863761	863761
QCIXP1200GA 863760	863760
QCIXP1240AC 863769	863769
QCIXP1240AB 863764	863764
QCIXP1250BC 864650	864650
QCIXP1250BB 864649	864649
QCIXP1250BA 864648	864648
QCIXP1250BAT 865651	864651

Reference Documents / Attachments:

Document: _____ Location #: _____

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
March 15, 2007	00	Originally Published PCN
March 22, 2007	01	Replace IXP1250 with IXP12xx for Clarification Purposes