



Product Change Notification

106910 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106910 - 00
Change Title: SR4850HW4M,SHW4URM3AS,SR6850HW4M
and SHW6URM3AS, PCN 106910-00, Product
Marking, Class 2: Resource CD update
Date of Publication: November 03, 2006

Key Characteristics of the Change:

Product Marking

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Nov 17, 2006
---	--------------

Description of Change to the Customer:

Resource CD updates for update the drivers, utilities, documentation.

SR4850HW4M (SHW4URM)

Change the MM# from 877222 to 879454

Change top assembly part number from D35286-004 to D35286-005

Change CDA part number from C91330-007 to C91330-008

Change CD part number from C91332-007 to C91332-008

SHW4URM3SA

Change the MM# from 881586 to 886995

Change top assembly part number from D46299-001 to D46299-002

Change CDA part number from C91330-007 to C91330-008

Change CD part number from C91332-007 to C91332-008

SR6850HW4M (SHW6URM)

Change the MM# from 877219 to 879452

Change top assembly part number from D35289-002 to D35289-003

Change CDA part number from C91330-007 to C91330-008

Change CD part number from C91332-007 to C91332-008

SHW6URM3SA

Change the MM# from 881402 to 887385

Change top assembly part number D46296-001 to D46296-002

Change CDA part number from C91330-007 to C91330-008

Change CD part number from C91332-007 to C91332-008

Customer Impact of Change and Recommended Action:

No significant impact on product/process/material performance, appearance, quality, reliability, interchangeability, functionality or customer handling and manufacturability.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Post Change MM#	Post Change TA
SHW4URM 877222	877222	D35286-004	879454	D35286-005
SHW6URM 877219	877219	D35289-002	879452	D35289-003
SHW4URM3SA 881586	881586	D46299-001	887385	D46299-002
SHW6URM3SA 881402	881402	D46296-001	886995	D46296-002

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

November 3, 2006

00

Originally Published PCN