



Product Change Notification

106810 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106810 - 00
Change Title: D865GSA, PCN 106810-00, Product Design, Enhancement with ESD varistor
Date of Publication: September 28, 2006

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Oct 19, 2006
---	--------------

Description of Change to the Customer:

The D865GSA desktop board is being enhanced with ESD varistor for better protection to integrated graphics

Customer Impact of Change and Recommended Action:

This board change is not expected to cause a change to the Microsoft* Windows* operating system's software driver stack.

This change are being thoroughly evaluated to ensure that there is no quality, reliability or functional implications to our customers. NO additional qualification is recommended for this change on platforms received from Intel.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change CA	Pre Change AA	Pre Change PBA	Post Change Product Code	Post Change MM#	Post Change TA	Post Change CA	Post Change AA	Post Change PBA
LAD865GSAL881405	881405	No change	No change	D52278-202 rev:03	No change	No change	No change	No change	No change	D52278-203	No change
BLKD865GSAL881941	881941	No change	No change	D53275-202 rev:02	No change	No change	No change	No change	No change	D53275-203	No change
BOXD865GSAL881942	881942	No change	No change	D53275-202 rev:02	No change	No change	No change	No change	No change	D53275-203	No change

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

September 28, 2006

Revision Number:

00

Reason:

Originally Published PCN