



Product Change Notification

106927 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106927 - 00
Change Title: SHW4URM23,SHW6URM23 and
SHW4URM2SA23, PCN 106927-00,
Manufacturing Site, Class 2: Accessories
FHWSATAIDE- board hole shape change
Date of Publication: November 06, 2006

Key Characteristics of the Change:

Manufacturing Site

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Dec 01, 2006
---	--------------

Description of Change to the Customer:

SHW4URM23

Change the MM# from 877218 to 886993

Change top assembly part number from D35288-006 to D35288-007

Change SATA-IDE board part number from C71688-002 to C71688-003

SHW6URM23

Change the MM# from 877217 to 886994

Change top assembly part number from D35290-004 to D35290-005

Change SATA-IDE board part number from C71688-002 to C71688-003

Change the J1 power connector PTH hole pattern change on SATA Bridge board to allow for better solder fill and flow.

Customer Impact of Change and Recommended Action:

No significant impact on product/process/material performance, appearance, quality, reliability, interchangeability, functionality or customer handling and manufacturability.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Post Change MM#	Post Change TA
SHW6URM23	877217	D35290-004	886993	D35290-005
SHW4URM23	877218	D35288-006	886994	D35288-007

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

November 6, 2006

Revision Number:

00

Reason:

Originally Published PCN