



Product Change Notification

107972 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107972 - 01
Change Title: DG965OT, PCN 107972-01, Product Design, BIOS update, Reason for Revision: Remove Intel® ViiV™ update notice.
Date of Publication: October 25, 2007

Key Characteristics of the Change: Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Nov 08, 2007
---	--------------

Description of Change to the Customer:

Reason for Revision: Remove Intel(C) ViiV(TM) update notice.

Update BIOS to MQ96510J,86A.1705.
Please refer to the release notes posted at
<http://developer.intel.com/products/motherboard/DG965OT/tools.htm> .

Customer Impact of Change and Recommended Action:

It is recommended that customers evaluate this new BIOS to ensure a smooth transition.

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. Intel is not recommending additional qualification of these changes on platforms received from Intel. This change is not expected to cause a change to the Microsoft* Windows* operating system's software driver stack. No expected OS image change.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change AA	Post Change AA
LADG965OTKR	878116	D41021-207	D41021-208
BOXDG965OTMKR	885058	D63733-207	D63733-208
BLKDG965OTMKR	885059	D63733-207	D63733-208

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
October 8, 2007	00	Originally Published PCN
October 25, 2007	01	Remove Intel® ViiV™ update notice.