



Product Change Notification

107502 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107502 - 02
Change Title: SR1530CL; SR1530HCL; SR153HCLS, PCN 107502-02, Product Material, Class 2; System Board Update, Reason for Revision: TA Revision change
Date of Publication: May 29, 2007

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jun 15, 2007
---	--------------

Description of Change to the Customer:

Reason for Revision: TA Revision change

Intel(R) Server System SR1530CL (SATA) board update with BIOS 76 - see BIOS release notes for details.
Intel(R) Server System SR1530HCL (SATA) board update with BIOS 76 - - see BIOS release notes for details.
Intel (R) Server System SR1530HCLS (SAS) board update with BIOS 76 and LSI SAS controller Stepping change from B1 to B2 to support NCQ (Native Command Queuing) - see BIOS release notes for details. .

Customer Impact of Change and Recommended Action:

Intel anticipates no customer impact for this change. Evaluate when available.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Post Change TA	Pre Change PBA	Post Change PBA
SR1530HCL	886910	D68877-004	D68877-005	D41874-603	D41874-604
SR1530HCL NA	887390	D68877-004	D68877-005	D41874-603	D41874-604
SR1530HCLS	887244	D68878-004	D68878-005	D24481-603	D24481-604
SR1530HCLSNA	887391	D68878-004	D68878-005	D24481-603	D24481-604
SR1530CL	888004	D64476-004	D64476-005	D41874-603	D41874-604
SR1530CLNA	888070	D64476-004	D64476-005	D41874-603	D41874-604

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

April 23, 2007

00

Originally Published PCN

May 18, 2007

01

Updating BIOS

May 29, 2007

02

TA Revision change