



Product Change Notification

106745 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106745 - 01
Change Title: SR1500, SR2500, SR1550, Class 1, PCN 106745-01, Product Design, Baseboard, Quick Start Guide, Reason for Revision: Correct Post Change MM# for SR1550AL, Correct Pre Change MCH stepping from B1 to B3
Date of Publication: September 18, 2006

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Sep 29, 2006
---	--------------

Description of Change to the Customer:

Reason for Revision: Correct Post Change MM# for SR1550AL, Correct Pre Change MCH stepping from B1 to B3

Change 1) Baseboard from -703 to -801
MCH changes from B3 to G1 stepping
Integrate wire from change 2 in PCN# 106415
System Software programmed at the factory is being updated.
BIOS - From R45 to R59
BMC Firmware - From R46 to R52
FRUSDR - From R32 to R36

The system software updates, including release notes for each, are available for download from Intel's secure web site, and from Intel's support website:-

<http://support.intel.com/support/motherboards/server/S5000PAL/>

Note:- This change only applies to product codes which include a motherboard.

Change 2) Quick Start Guide from -003 to -004

Note:- This change does not apply to SR1550 products

Customer Impact of Change and Recommended Action:

Customers may want to perform re-qualification, re-test, re-certification or standard validation testing for this change.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Post Change MM#	Post Change TA
SR1500ALSAS	880902	D47497-004	885481	D47497-005
SR1500AL	881038	D47500-004	885480	D47500-005
SR2500ALLX	881102	D43690-006	885489	D43690-007
SR2500ALBRP	881104	D43693-004	885488	D43693-005
SR1550ALSAS	881682	D50323-003	885485	D50323-004
SR1550AL	881684	D50324-002	885484	D50324-003
SR2500ALOEM	881896	D51593-007	885496	D51593-008
SR1500ALNA	881893	D47500-004	885482	D47500-005
SR1500ALSASNA	881892	D47497-004	885483	D47497-005
SR1550ALNA	881751	D50324-002	885486	D50324-003
SR1550ALSASNA	881750	D50323-003	885487	D50323-004
SR2500ALLXNA	881895	D43690-006	885499	D43690-007
SR2500ALBRPNA	881894	D43693-004	885498	D43693-005
SR2500ALOEMNA	882349	D51593-007	885500	D51593-008

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

September 7, 2006

September 18, 2006

Revision Number:

00

01

Reason:

Originally Published PCN

Correct Post Change MM# for SR1550AL, Correct Pre Change MCH stepping from B1 to B3