



Product Change Notification

107981 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107981 - 00
Change Title: Intel NetStructure® MPCBL0050N02Q
Single Board Computer, PCN 107981-00,
Product Design, Fabric Ports' Gigabit
Ethernet Controller EEPROM change.
Date of Publication: October 10, 2007

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Nov 15, 2007
---	--------------

Description of Change to the Customer:

Changed Intel® 82571EB Gigabit Ethernet Controller adapter firmware image from version 5.12 to version 1.3.0 (note that versioning system has changed). The new firmware image improves GbE activity and Link Up/Down LED signals handling.

Customer Impact of Change and Recommended Action:

No customer action required.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
MPCBL0050N02Q	887727	D88583-005	D98058-002	D88583-006	D98058-002
MPCBL0050S01Q	887996	E15129-002	D98058-002	E15129-003	D98058-002

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

October 10, 2007

Revision Number:

00

Reason:

Originally Published PCN