



Product Change Notification

106613 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106613 - 00

**Change Title: BLKD945GPMLKR,
BOXD945GPMLKR, PCN 106613-
00, Product Material, Add RoHS
label for PRC and alternate part for
SIO**

Date of Publication: April 06, 2007

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Apr 26, 2007
---	--------------

Description of Change to the Customer:

Add the RoHS markings to the BLKD945GPMLKR and BOXD945GPMLKR Intel Desktop Board as a requirement for the People's Republic of China for retail products manufactured on or after 1 March 2007. The markings will appear as a label on the component side of the printed circuit board and on the motherboard packaging as well.

An alternate part for SIO has been added to ensure component supply availability for manufacturing.

Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. CDPG is not recommending additional qualification of these changes on platforms received from Intel. These board changes are not expected to cause a change to the Microsoft* Windows* operating system's software driver stack. No expected OS image change.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change AA	Pre Change PBA	Post Change TA	Post Change AA	Post Change PBA
BLKD945GPMLKR 874678	874678	D28141- 107	D21427- 107	D21428- 107	D28141- 108	D21427- 108	D21428- 108
BOXD945GPMLKR 874683	874683	28145- 106	D21427- 107	D21428- 107	D28145- 107	D21427- 108	D21428- 108

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

April 6, 2007

Revision Number:

00

Reason:

Originally Published PCN