



Product Change Notification

109236 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: <mailto:asmo.pcn@intel.com>

Asia Pacific Contact: <mailto:apacgccb@intel.com>

Europe Email: <mailto:eccb@intel.com>

Japan Email: <mailto:jccb.ijkk@intel.com>

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109236 - 01
Change Title: Intel(R) Server Board S5400SF, PCN 109236-01, Product Design, Update the system baseboard, Reason for Revision: Add detail description for the change
Date of Publication: March 03, 2009

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Mar 20, 2009
---	--------------

Description of Change to the Customer:

Reason for Revision: Add detail description for the change

Update the baseboard include replacing bridge board connector and removing ICT test cap/resistors.

1. The bridge board connector (J4G1) is being replaced with a new connector that has improved surface connector depth;
2. The following components are being removed from the server board:
C2K5;C8V7;C8V3;C8V13;C3B9;C2L1;C7W2;C3B10;C6N1;C2B4;C8V5;C8V4;C7W6;
C3D1;C8V1;C8V10;C8V11;C6T7;C6T10;C8V8;C8V6;R6U1;R8V27;R8V18;R8V29;
R4L14;R8V1;R8V4;R8V16;R8V26;R8V25;R2B6;R7V6;R8V20;R8V21;R8V13;
R8V32;R8V12;R8V24;R8V22;R8V5;R7V5;R8V15;R2L1;R6Y11;R2K2;R8V2;R5U6;
R8V3;R8V31;R6U3;R8V14;R1C1;R7P1;R7T2;R8V6;R3D4;R8V30;R8V33;R2Y1.

These components were only used for factory test purposes, therefore they have no affect on board functionality.

Customer Impact of Change and Recommended Action:

Customers may want to evaluate the server board with the new bridge board connector when available.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
BB5400SF	892604	E15540-406	D87491-406	E15540-407	D87491-407

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

February 26, 2009

March 3, 2009

Revision Number:

00

01

Reason:

Originally Published PCN

Add detail description for the
change