



Product Change Notification

109221 - 02

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

America's OEM's Contact:

Krista Gottschalk Phone:(503) 712-8026 Email: krista.r.gottschalk@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109221 - 02
Change Title: Intel® WiFi Link 5000 Series Generic Skus:
512AN_HMWG, HMWG2, MMWG,
MMWG2, MMWW, MMWW2;
533AN_HMWG, HMWG2, MMWG,
MMWG2, MMWW, MMWW2;
512AG_HMWG, HMWG2,
PCN 109221-02, Label, Transport Media,
Add DSPR logo, Korea logo, update carton
logo, Reason for Revision: Inventory
Management
Date of Publication: March 11, 2009

Key Characteristics of the Change:

Label

Forecasted Key Milestones:

	512AN_MMWG2, 512_MMWW,512AN_MMWW2	ALL OTHER PRODUCTS
Date Customer Must be Ready to Receive Post-Conversion Material:	May 01, 2009	Feb 27, 2009
Date of First Availability of Post-Conversion Material:	May 01, 2009	Feb 27, 2009

The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.

Description of Change to the Customer:

Rev02

Reason for Revision: Inventory Management

In order to better align with Intel inventory management requirements, Intel has revised the implementation date for this PCN. Please refer to the Forecasted Key Milestone section of the PCN for first availability of post-conversion material dates.

Rev01

Reason for Revision: Correction to Product Code for MM#900231

1. Add DSPR logo on all SP AGN SKUs.
2. Add Korea logo on all SP MC1x2 and MC3x3 AGN SKUs.
3. Update carton logo placement on SP HMC carton boxes.

Rev00

1. Add DSPR logo on all SP AGN SKUs.
2. Add Korea logo on all SP MC1x2 and MC3x3 AGN SKUs.
3. Update carton logo placement on SP HMC carton boxes.

Customer Impact of Change and Recommended Action:

Customer will receive product with the following changes:

Rev02

Milestone dates updated per the Forecasted Key Milestones in this PCN


Rev01

Reason for Revision: Correction to Product Code for MM#900231 in the Board Products Table

1. DSPR logo added on all SP AGN SKUs.
2. Korea logo added on all SP MC1x2 and MC3x3 AGN SKUs.
3. Carton logo placement updated on SP HMC carton

Rev00

1. DSPR logo added on all SP AGN SKUs.
2. Korea logo added on all SP MC1x2 and MC3x3 AGN SKUs.
3. Carton logo placement updated on SP HMC carton



Intel will attempt to deplete pre-conversion material before shipping post-conversion material but there is a possibility of Intel shipping mixed inventory. Therefore, customers will need to manage and migrate to the post-conversion material as soon as possible.

Intel will attempt to deplete pre-conversion material before shipping post-conversion material but there is a possibility of Intel shipping mixed inventory. Therefore, customers will need to manage and migrate to the post-conversion material as soon as possible.

For your information only. No change to form, fit or function. No change to Intel Ordering codes.

Milestone dates are estimates and subject to change based on business and operational conditions.

**Products Affected / Intel Ordering Codes:
Board Products Table**

512AN_HMWG, HMWG2, MMWG; 533AN_HMWG, HMWG2, MMWG, MMWG2, MMWW, MMWW2, 512AG_HMWG; 512AG.HMWG2				
Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA
512AN_HMWG	895373	895373	E14740-014	E14740-015
512AN_HMWG2	899555	899555	E50455-004	E50455-005
512AN_MMWG	895361	895361	E14718-014	E14718-015
512AG_HMWG	897072	897072	E32467-007	E32467-008
512AG.HMWG2	900231	900231	E51055-005	E51055-006
533AN_HMWG	895401	895401	E14702-012	E14702-013
533AN_HMWG2	899547	899547	E50448-002	E50448-003
533AN_MMWG	895362	895362	E14698-013	E14698-014
533AN_MMWG2	899545	899545	E50447-002	E50447-003
533AN_MMWW	897774	897774	E39125-005	E39125-006
533AN_MMWW2	899554	899554	E50454-002	E50454-003

512AN_MMWG2, 512_MMWW, 512AN_MMWW2				
Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA
512AN_MMWG2	899541	899541	E50443-004	E50443-005
512AN_MMWW	897801	897801	E39126-006	E39126-007
512AN_MMWW2	899553	899553	E50457-004	E50457-005

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
February 20, 2009	00	Originally Published PCN
February 23, 2009	01	Correction to Product Code for MM#900231
March 11, 2009	02	Inventory Management