



# Product Change Notification

## 105818 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

AlertVIEW, AnyPoint, AppChoice, EtherExpress, FlashFile, i386, i486, i960, Intel, Celeron, Intel486, Intel740, IntelDX2, IntelDX4, IntelSX2, Itanium, LANDesk, LanRover, Pentium, Xeon, Intel Xeon, NetMerge, NetStructure, OverDrive, Paragon, PDCharm, StrataFlash is a trademark or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 105818 - 00  
**Change Title:** SR4850HW4 and SR6850HW4 - Accessories  
AHWIMMPRO2 and AHWIMMADV2,  
PCN 105818-00, FYI,  
**CLASS 2: Update the BMC firmware on the  
AHWIMMPRO2 and AHWIMMADV2**  
**Date of Publication:** January 10, 2006

**Type of Change Notification:**  
FYI - (For Your Information)

**Key Characteristics of the Change:**  
Software

## Forecasted Key Milestones:

<b>Date of First Availability of Post-Conversion Material:</b>	Dec 30, 2005
--	--------------

*The date of "First Availability of Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Intel will continue to ship and customers may continue to receive the pre-converted materials until the inventory has been depleted.*

## Description of Change to the Customer:

The following system level software update has been implemented on the Accessory AHWIMMADV2:

873661

Change the top assembly part number from D21853-002 to D21853-003  
Change the IMM Board number from D23071-401 to D23071-402  
-BMC firmware 43

The following system level software update will be implemented on the Accessory AHWIMMPRO2:

873662

Change the top assembly part number from D21857-002 to D21857-003  
Change the IMM Board number from D23013-401 to D23013-402  
-BMC firmware 43

## Customer Impact of Change and Recommended Action:

No significant impact on product/process/material performance, appearance, quality, reliability, interchangeability, functionality or customer handling and manufacturability.

## Products Affected / Intel Ordering Codes:

### Board Products Table

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA or AA	Post-Change TA or AA	Pre-Change PBA	Post-Change PBA
AHWIMMADV2	873661	873661	D21853-002	D21853-003	D23071-401	D23071-402
AHWIMMPRO2	873662	873662	D21857-002	D21857-003	D23013-401	D23013-402

## Reference Documents / Attachments:

Document:

Location #:

## PCN Revision History:

Date of Revision:

Revision Number:

Reason:

January 10, 2006

00

Originally Published PCN