



Product Change Notification

109454 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

America's OEM's Contact:

Krista Gottschalk Phone:(503) 712-8026 Email: krista.r.gottschalk@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109454 - 00
Change Title: Intel® Wireless WiFi Link 4965AGN/AG
Skus: 4965AGNMM1GN, M2GN, RWGN,
JPGN, KRGN, M1WB, M2WB, RWWB,
JPWB, KRG2; 4965AG_MM1GN, M2GN,
RWGN, JPGN2,
PCN 109454-00, Product Discontinuance
Date of Publication: June 26, 2009

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

| | |
|---|--------------|
| Product Discontinuance Demand To Local Intel Representative: | Aug 21, 2009 |
| Orders are Non-Cancelable and Non-Returnable After: | Aug 21, 2009 |
| Last Corporate Commit Product Hot List Date: | Sep 18, 2009 |
| Last Product Discontinuance Order Date: | Oct 16, 2009 |
| Last Product Discontinuance Shipment Date: | Dec 10, 2010 |

Description of Change to the Customer:

Intel® Wireless WiFi Link 4965AGN/AG hardware (product codes listed below) will be discontinued on October 16, 2009. Intel will focus its efforts on current and future WiFi and WiMAX module products including: the Intel® WiFi Link 5000 Series, Intel® WiMAX/WiFi Link 5150, Intel® Centrino Wireless-N 1000, Intel® Centrino Advanced-N 6200, Intel® Centrino Ultimate-N 6300 and Intel® Centrino Advanced-N + WiMAX 6250.

ALL FINAL PRODUCT DEMAND AND ORDERS ARE NON-CANCELABLE, NON-RETURNABLE AFTER AUGUST 21, 2009.

Customer Impact of Change and Recommended Action:

Intel® Wireless WiFi Link 4965AGN/AG hardware (product codes listed below) will be discontinued on October 16, 2009. Intel will continue to focus its efforts on current and future WiFi and WiMAX module products including: the Intel® WiFi Link 5000 Series, Intel® WiMAX/WiFi Link 5150, Intel® Centrino Wireless-N 1000, Intel® Centrino Advanced-N 6200, Intel® Centrino Ultimate-N 6300 and Intel® Centrino Advanced-N + WiMAX 6250.

Customers wishing to order Intel® Wireless WiFi Link 4965AGN/AG products must have final orders placed with Intel by October 16, 2009. Effective December 10, 2010 Intel will stop shipping Intel® Wireless WiFi Link 4965AGN/AG hardware.

ALL FINAL PRODUCT DEMAND AND ORDERS ARE NON-CANCELABLE, NON-RETURNABLE AFTER August 21, 2009.

Milestone dates are estimates and subject to change based on business and operational conditions.

Products Affected / Intel Ordering Codes:

| Affected Product Code | Affected MM# |
|-----------------------|--------------|
| 4965AGNMM1GN | 886224 |
| 4965AGNMM2GN | 886220 |
| 4965AGNMRWGN | 886434 |
| 4965AGNMJPGN | 886437 |
| 4965AGNMKRGN | 888121 |
| 4965AGNMM1WB | 886704 |
| 4965AGNMM2WB | 886734 |
| 4965AGNMRWWB | 886727 |
| 4965AGNMJPWB | 886732 |
| 4965AG_MM1GN | 886449 |
| 4965AG_MM2GN | 886450 |
| 4965AG_MRWGN | 886451 |
| 4965AG_MJPGN2 | 892228 |
| 4965AGNMKRG2 | 896900 |

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

June 26, 2009

Revision Number:

00

Reason:

Originally Published PCN