



Product Change Notification

Change Notification #: 854898-00

Change Title: Select Intel® Ethernet Network Adapters

Change Detail: Product Label and Marking Update: FCC and Canadian Compliance

Date of Publication: May 19, 2025

Key Characteristics of the Change:

Product Marking, Label

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material	June 03, 2025
--	---------------

Description of Change to the Customer:

The Intel® SKUs listed in the products affected table below will be updated with the following change(s):

1. After additional testing, Intel has confirmed that these products meet FCC Class B emissions compliance requirements.
2. The CAN ICES marking on affected product is being updated from CAN ICES-3(A)/NMB-3(A) to Class B CAN ICES-3(B)/NMB-3(B) to ensure continued compliance with Canadian EMI regulations. This change will be implemented in two stages:
 - Interim Labeling Approach: A Class B printed cover-up label will be applied over the existing Class A silkscreen marking on current PCB inventory.
 - Permanent Marking Update: Once existing PCB inventory is depleted, new PCBs will be introduced with Class B marking directly printed on the silkscreen. Customers should expect the TA# and PBA# to be further rolled up compared to the cover-up label version, as part of the permanent silkscreen marking.

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers.

Please contact your local Intel Field Sales Rep if you have any further questions about these changes.

Products Affected/Intel Ordering Codes:

Marketing Name	Product Code	MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
Intel® Ethernet Network Adapter E610-IT4, Multi	E610IT4M5	99CGT0	N56056-001	N55484-002	N56056-002 (Cover up label) N56056-003 (Silkscreen)	N55484-003 (Cover up label) N55484-004 (Silkscreen)
Intel® Ethernet Network Adapter E610-IT4, Single	E610IT4	99C5F1	M94094-001	N55484-002	M94094-002 (Cover up label) M94094-003 (Silkscreen)	N55484-003 (Cover up label) N55484-004 (Silkscreen)
Intel® Ethernet Network Adapter E610-XT2, Multi	E610XT2M5	99CFRF	N48010-001	N42545-004	N48010-002 (Cover up label) N48010-003 (Silkscreen)	N42545-005 (Cover up label) N42545-006 (Silkscreen)
Intel® Ethernet Network Adapter E610-XT4, Multi	E610XT4M5	99CFRH	N42548-001	N23673-004	N42548-002 (Cover Up label) N42548-003 (Silkscreen)	N23673-005 (Cover up label) N23673-006 (Silkscreen)
Intel® Ethernet Network Adapter E610-XT4, Single	E610XT4	99CFRG	N55625-001	N23673-004	N55625-002 (Cover Up label) N55625-003 (Silkscreen)	N23673-005 (Cover up label) N23673-006 (Silkscreen)
Intel® Ethernet Network Adapter E610-XT2, Single	E610XT2	99CFRD	N56055-001	N42545-004	N56055-002 (Cover up label) N56055-003 (Silkscreen)	N42545-005 (Cover up label) N42545-006 (Silkscreen)

PCN Revision History:

Date of Revision:

May 19, 2025

Revision Number:

00

Reason:

Originally Published PCN



Product Change Notification

854898-00

Notices & Disclaimers

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade, except as provided in a separate written agreement.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes the subject matter disclosed herein.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Statements in this document that refer to future plans or expectations are forward-looking statements. These statements are based on current expectations and involve many risks and uncertainties that could cause actual results to differ materially from those expressed or implied in such statements. For more information on the factors that could cause actual results to differ materially, see our most recent earnings release and SEC filings at www.intc.com.

Customer is responsible for safety of the overall system, including compliance with applicable safety-related requirements or standards.

Intel technologies may require enabled hardware, software or service activation.

No product or component can be absolutely secure.

Your costs and results may vary.

©Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.

No response from customers will be deemed an acceptance of the change, and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com